



Oregon State University

**Construction Contracts
Administration, Procurement
Contracts & Materials
Management (PCMM)**
Oregon State University
644 SW 13th Ave.
Corvallis, Oregon 97333

**P 541-737-4261
F 541-737-5546
oregonstate.edu**

2/19/2019

Oregon State University
Construction Contract Administration
Finley Hall Roof Replacement

ADDENDUM NO. 2

THIS ADDENDUM IS BEING ISSUED for clarification and/or revisions of the drawings and specifications as noted. This document is hereby made a part of the Contract Documents to the extent as though it was originally included herein.

Questions/Answers:

- Item 1 **Question:** What are the specification section for metals? This would include the metal threshold on A8.3 and the pipe rail material and finish.
Answer: For the door threshold, refer to Detail 4/A8.3 (no additional specification section required). For the pipe rail, refer to sheet S5.2, Details 1&2.
- Item 2 **Question:** What is the specification section for concrete? This would cover the concrete infill for the roof.
Answer: For concrete, refer to Sheet S0.2 (concrete mix design), and Sheet S5.2 Detail 3.
- Item 3 **Question:** On A1.0, A3.1 and A3.2 there are notes for bike racks, brick infill, CMU screen wall and concrete ramp and handrail. The sheets say for reference only – please confirm there is no scope for those items.
Answer: Confirmed, no scope items.
- Item 4 **Question:** P103 shows one less vent unit – is V/5 missing from the demo plan or is it newly added?
Answer: Sheet 203(Roof Plan) is correct.
- Item 5 **Question:** 112 laundry vent is shown as existing but not indicated on P203 or any other sheet in the document set.
Answer: There is an existing laundry vent, but it's located on the first floor exterior wall. No scope for the roof replacement project.

END OF ADDENDUM NO. 2